CLEANMAT TRUCKS
+31 (0)488 712 600 sales@cleanmat.eu
Wageningsestraat 17, 6673 DB Andelst, Nederland

Mercedes-Benz Sprinter 516 CD Camerawagen / Inspectie / Diagnose

ID number	**46215**
1st registration	**05-04-2013**
Mileage	**81475**
Year	**2013**
Chassis number	**WDB9066551S771731**
Fuel	**Petrol**
Euro norm	**Euro 5**
Engine power	**163hp / 120kw**
Transmission	**Manual**

€29.000

Accessoires

- Airconditioning
- Anti-lock braking system
- Electrically operated windows
- Radio/CD player
- Reversing camera

Comments

- Camera vehicle / Inspection / Diagnostic unit
- Inspection unit type IBAK Modular BS7
- Full control via joysticks and keyboard
- IBAK winch with cable length approx. 500 meters
- Ergonomic control console with configurable controls
- Equipped with all accessories such as control unit, monitor, printer etc.
- Converter Victron Energy Multiplus
- Sliding door right
- Just 81.475 km!
- Ex-municipal vehicle!

+31 (0)488 712 600 sales@cleanmat.eu
Wageningsestraat 17, 6673 DB Andelst, Nederland

General

Dimensions	**710 x 200 x 260**
Overall condition	**Good**
Technical condition	**Good**
Optical condition	**Good**

Chassis

Own weight (kg)	**4300**
Loading capacity (kg)	**700**
GVW (kg)	**5000**
Wheelbase (kg)	**430**

Powertrain

Transmission	**Manual**
Cylinder capacity (cc)	**2143**
Engine power (pk)	**163**
Engine power (kw)	**120**

Axle configuration (4x2)

Tire size	1	1
Profile Left/Right	50	60
Suspension	vehicle.parabool	Leaf
Maximum axle load	2000	3500
Reduction	-	Single
Axle lift	✖	✖
Steering	✔	✖
Powered	✖	✔

All prices are excluding VAT

All specifications are subject to change. The given mileage, sizes, weights and other specifications are not legally binding